

1" galvanized domestic hot water return, low level



1 1/2" galvanized domestic hot water supply

DIHYDRO/USI
15 02 P

1 1/4" carbon steel hot water heating return

- Serious pitting under mounds of existing scale extending from the pipe surface .062" to .375"...restricting flow by 30%
- This X-ray image shows three major pits in the pipe wall 55 to 85%