



- X-Ray no.76 : Mechanical Room
- 4 in. x 2 1/2 in. x 3 in. bushing
- 2 1/2 in. nipple Cold water
- Leaks at 2 1/2 in. nipple at wall

- Standard pipe wall thickness: .203/.203
- Wall thickness reading: .120

- Leak at the 2 1/2 in. nipple wall penetration
- 3 in. diameter bushing wall loss 40-65%
- Nipple wall is penetrated and leaking
- Scale covers the I.D.
- This section needs to be repaired